L Number	Hits	Search Text	DB	Time stamp
1	271	702/104.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 09:24
8	25	702/104.ccls. and (measur$5 or determin$3 or detect$3 or obtain$3) with position$3 with (element$1 or object$1 or tool$1 or workpiece$1)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 09:26
-	156907	(measur$5 or determin$3 or detect$3 or obtain$3) with position$3 with (element$1 or object$1 or tool$1 or workpiece$1)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 09:24
-	590	((measur$5 or determin$3 or detect$3 or obtain$3) with position$3 with (element$1 or object$1 or tool$1 or workpiece$1)) and ((voltage with monitor$3) and scan$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 22:40
-	263	(((measur$5 or determin$3 or detect$3 or obtain$3) with position$3 with (element$1 or object$1 or tool$1 or workpiece$1)) and ((voltage with monitor$3) and scan$4)) and ((element$1 or object$1) with (movable or moving or movement))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 22:42
-	185	((((measur$5 or determin$3 or detect$3 or obtain$3) with position$3 with (element$1 or object$1 or tool$1 or workpiece$1)) and ((voltage with monitor$3) and scan$4)) and ((element$1 or object$1) with (movable or moving or movement))) and ((suppl$3 with voltage) or (voltage with source))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 22:26
-	1	(((((measur$5 or determin$3 or detect$3 or obtain$3) with position$3 with (element$1 or object$1 or tool$1 or workpiece$1)) and ((voltage with monitor$3) and scan$4)) and ((element$1 or object$1) with (movable or moving or movement))) and ((suppl$3 with voltage) or (voltage with source))) and ((scanning adj unit) with (position with calculat$3))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 22:32
-	3	(((((measur$5 or determin$3 or detect$3 or obtain$3) with position$3 with (element$1 or object$1 or tool$1 or workpiece$1)) and ((voltage with monitor$3) and scan$4)) and ((element$1 or object$1) with (movable or moving or movement))) and ((suppl$3 with voltage) or (voltage with source))) and (scanning adj unit)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 22:32
-	69492	(measur$5 or determin$3 or detect$3 or obtain$3 or monitor$3) with position$3 with (elements or objects or tools or workpiece$1 or units)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 22:39
-	234	((measur$5 or determin$3 or detect$3 or obtain$3 or monitor$3) with position$3 with (elements or objects or tools or workpiece$1 or units)) and (voltage with (suppl$3 or source) with scan$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 00:08
-	112	(((measur$5 or determin$3 or detect$3 or obtain$3 or monitor$3) with position$3 with (elements or objects or tools or workpiece$1 or units)) and (voltage with (suppl$3 or source) with scan$4)) and ((element$1 or object$1 or tool$1) with (movable or moving or movement))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 22:43

-	53	((((measur$5 or determin$3 or detect$3 or obtain$3 or monitor$3) with position$3 with (elements or objects or tools or workpiece$1 or units)) and (voltage with (suppl$3 or source) with scan$4)) and ((element$1 or object$1 or tool$1) with (movable or moving or movement))) and (calculat$3 or evaluat$3)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:01
-	3	(((((measur$5 or determin$3 or detect$3 or obtain$3 or monitor$3) with position$3 with (elements or objects or tools or workpiece$1 or units)) and (voltage with (suppl$3 or source) with scan$4)) and ((element$1 or object$1 or tool$1) with (movable or moving or movement))) and (calculat$3 or evaluat$3)) and (((start adj up) or (start-up) or (switch$3 with on) or (turn$3 with on) or initial$2) same ((check$3 or inspect$3 or verify$4) with voltage))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:11
-	1	(((((measur$5 or determin$3 or detect$3 or obtain$3 or monitor$3) with position$3 with (elements or objects or tools or workpiece$1 or units)) and (voltage with (suppl$3 or source) with scan$4)) and ((element$1 or object$1 or tool$1) with (movable or moving or movement))) and (calculat$3 or evaluat$3)) and (((start adj up) or (start-up) or (switch$3 with on) or (turn$3 with on) or initial$2 or (power adj up) or (power adj on)) same ((check$3 or inspect$3 or verify$4 or examin$3) with voltage with scan$4))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:35
-	9	(((measur$5 or determin$3 or detect$3 or obtain$3 or monitor$3) with position$3 with (elements or objects or tools or workpiece$1 or units)) and (voltage with (suppl$3 or source) with scan$4)) and (((start adj up) or (start-up) or (switch$3 with on) or (turn$3 with on) or initial$2 or (power adj up) or (power adj on)) same ((check$3 or inspect$3 or verify$4 or examin$3 or measur$5) with voltage))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:25
-	217	((measur$5 or determin$3 or detect$3 or obtain$3 or monitor$3) with position$3 with (elements or objects or tools or workpiece$1 or units)) and (((start adj up) or (start-up) or (switch$3 with on) or (turn$3 with on) or initial$2 or (power adj up) or (power adj on)) same ((check$3 or inspect$3 or verify$4 or examin$3 or measur$5) with voltage))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:27
-	20	((measur$5 or determin$3 or detect$3 or obtain$3 or monitor$3) with position$3 with (elements or objects or tools or workpiece$1 or units)) and (((start adj up) or (start-up) or (switch$3 with on) or (turn$3 with on) or (power adj up) or (power adj on)) same ((check$3 or inspect$3 or verify$4 or examin$3 or measur$5) with voltage))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:28
-	796	((start adj up) or (start-up) or (switch$3 with on) or (turn$3 with on) or (power adj up) or (power adj on)) same ((check$3 or inspect$3 or verify$4 or examin$3 or monitor$3 or detect$3) with voltage with (suppl$2 or source))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:40

-	15	((((start adj up) or (start-up) or (switch$3 with on) or (turn$3 with on) or (power adj up) or (power adj on)) same ((check$3 or inspect$3 or verify$4 or examin$3 or monitor$3 or detect$3) with voltage with (suppl$2 or source))) and ((sufficient or stable) with voltage with supply)) and (position with (measur$5 or determin$4 or detect$3 or calculat$3 or evaluat$3))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:43
-	144	(((start adj up) or (start-up) or (switch$3 with on) or (turn$3 with on) or (power adj up) or (power adj on)) same ((check$3 or inspect$3 or verify$4 or examin$3 or monitor$3 or detect$3) with voltage with (suppl$2 or source))) and ((sufficient or stable) with voltage with supply)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:57
-	1	((((start adj up) or (start-up) or (switch$3 with on) or (turn$3 with on) or (power adj up) or (power adj on)) same ((check$3 or inspect$3 or verify$4 or examin$3 or monitor$3 or detect$3) with voltage with (suppl$2 or source))) and ((sufficient or stable) with voltage with supply)) and (defined with load with voltage)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:57
-	48	((((start adj up) or (start-up) or (switch$3 with on) or (turn$3 with on) or (power adj up) or (power adj on)) same ((check$3 or inspect$3 or verify$4 or examin$3 or monitor$3 or detect$3) with voltage with (suppl$2 or source))) and ((sufficient or stable) with voltage with supply)) and (load with voltage)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/11 23:58
-	28	(((((start adj up) or (start-up) or (switch$3 with on) or (turn$3 with on) or (power adj up) or (power adj on)) same ((check$3 or inspect$3 or verify$4 or examin$3 or monitor$3 or detect$3) with voltage with (suppl$2 or source))) and ((sufficient or stable) with voltage with supply)) and (load with voltage)) and (resistance)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 00:04
-	2	((((((start adj up) or (start-up) or (switch$3 with on) or (turn$3 with on) or (power adj up) or (power adj on)) same ((check$3 or inspect$3 or verify$4 or examin$3 or monitor$3 or detect$3) with voltage with (suppl$2 or source))) and ((sufficient or stable) with voltage with supply)) and (load with voltage)) and (resistance)) and (second adj time)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 00:04
-	41	((measur$5 or determin$3 or detect$3 or obtain$3 or monitor$3) with position$3 with (elements or objects or tools or workpiece$1 or units)) and (read$3 with graduation with position)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 00:09
-	15	(((measur$5 or determin$3 or detect$3 or obtain$3 or monitor$3) with position$3 with (elements or objects or tools or workpiece$1 or units)) and (read$3 with graduation with position)) and (light adj source)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 00:16
-	2	3644700.pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 00:16

-	4	4219719.pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 00:17
-	2	6462855.pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 00:18
-	1	"5995246".PN.	USPAT	2003/02/12 00:18
-	1	"5929891".PN.	USPAT	2003/02/12 00:18
-	2	6353397.pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/02/12 00:18
-	1	"6043768".PN.	USPAT	2003/02/12 00:19
-	1	"5532582".PN.	USPAT	2003/02/12 00:19
-	1	"5451940".PN.	USPAT	2003/02/12 00:19
-	1	"5012436".PN.	USPAT	2003/02/12 00:20